

The Campbell Group

Campbell Hausfeld • Wayne • Powerwinch

Instructions/Attach To:

USCN083

Date: 10/18/00

Page: 1 of 1

From: Consumer Engineering

Concerning: Repair of Millenium Compressors

Models Affected: WL650000AJ, WL650100AJ, WL650200AJ, WL650300AJ, WL650400AJ, WL660000AJ, WL660100AJ, WL660300AJ, WL660400AJ, WL611104AJ, WL604010AJ.

TO ALL AUTHORIZED SERVICE CENTERS:

When performing warranty repairs to the Millenium Air Compressor, please remove and return the Pump/Motor Decal. This decal can be found on the pump motor assembly shroud, and looks similar to the label found below. Please submit this decal until notified otherwise.



If you have questions, please call your customer service representative.
Thank you for your cooperation in this matter.

Product Service Department.