

The Campbell Group

Campbell Hausfeld • Wayne • Powerwinch

From: **Painting Systems**

Painting Systems Ref. # 9491

Concerning: Creation of AL2333 (AL233301LX)

Instructions/Attach To:

Behind Airless Tab

Date: ___04/12/99___

Page: ___1___ of ___1___

As of 2/11 99, the AL233300LX was rendered obsolete and replaced by the AL2333. The model/serial number decal on the units manufactured after this change show AL233301LX as the model (part) number. This occurred as a result of change to the motor, which in turn caused a change to the eccentric and the diaphragm.

Please note that this change made the motor, diaphragm and eccentric parts that can't be shared by the AL233300LX and the AL233301LX. In addition to the part number located in the model number field of the above referenced decal, the AL233301LX can also be identified by the length of it's motor. This new motor is substantially shorter than the AL233300LX motor and measures 7 ¾" from the bottom of the fan shroud to the top of the motor shell.

The new parts required for servicing the AL233301LX are:

- AL125801SV – Diaphragm
- AL116202SV – Eccentric/Bearing Kit

All other parts are exactly the same as used on all airless units, valves, block, housing, etc. The motor for this unit can be serviced with the MC014300SV service kit. This kit has been changed to include eccentric/bearing kit and the diaphragm, which makes it compatible with the remaining parts on the AL233301LX. This motor kit is also used on all other ½ horsepower diaphragm airless units.

The AL2333.... Style unit is pictured below. This bulletin only applies to units that look like the one pictured.

